

Windows Embedded CE 6.0 TI ARM-A8 BSP for

AM35xx/OMAP35xx/AM37xx/DM37xx

Version 01.02.00

# **Release Notes**

Table 1. Revision History

BSP Version	Date	Description
V 1.0.0	11/09/2010	Document creation
V 1.1.0	02/22/2011	BSP 01.01.00 update
V1.1.0.patch_01	03/25/2011	BSP 01.01.00 Patch 01 update
V1.2.0	05/16/2011	BSP 01.02.00 update

# Contents

1.	Tra	demarks	. 4
2.	Intr	oduction	. 4
3.	Nev	w Features	. 4
	3.1.	Rel 01_02_00	. 4
	3.2.	Rel 01_01_00 Patch 01	.5
	3.3.	Rel 01_01_00	. 5
4.	Dist	tribution Contents	. 7
5.	Inst	allation Instructions	. 7
6.	Rec	quirements	. 8
	6.1.	Required QFE's and Updates	.8
	6.2.	Hardware Requirement	.8
7.	Fea	ture Summary	.9
8.	Tes	t Summary	.9
9.	Lim	itations1	LO
	9.1.	BSP Limitations related to Hardware	LO
	9.2.	BSP Limitations related to Microsoft WinCE Kernel	l1
	9.3.	Other BSP Limitations	l1
10	). k	Known Issues	L2
11	l. S	Support1	L4

### 1. Trademarks

Windows and Microsoft are registered trademarks of Microsoft Corporation. All other trademarks are property of their respective owners.

#### 2. Introduction

This document provides information for TI ARM A8 WINCE 6.0 BSP release.

TI ARM\_A8 BSP is designed for TI AM35x processor family, OMAP35x processor family and AM/DM37x processor family.

It supports two platforms: the AM35x BSP, compatible with the LogicPD AM3517 eXperimenter Kit, and the OMAP35x BSP, compatible with OMAP 35x EVM Board(for both OMAP35x processor family) and AM/DM37x processor family).

OMAP35x processors and AM/DM37x processors share the same BSP, hence the same image can run on both processor families.

The BSP release contains the following packages:

- ARM A8 WINCE BSP for AM35x and OMAP35x EVM.
- DVSDK 01.11.00 release binaries
- PowerVR 3D Graphics 01.01.00 release binaries
- Prebuilt images , Tools and Documentation

For more information, please refer to the 'BSP\_WINCE\_ARM A8\_User\_Guide.pdf' file included in this release.

#### 3. New Features

## 3.1. Rel 01\_02\_00

Following features have been added to this release:

- 1. Support for BinFS and multiple bin. This feature helps in reducing the boot-up time.
- 2. Ability to change the CPU frequency from eboot.

Following bugs have been fixed in this release:

<u>ID</u>	<u>Headline</u>	
SDOCM00080831	(Enhancement) Allow user to change opm mode in DVFS enabled build without KITL	
SDOCM00080829	(Enhancement) Allow user to select CPU frequency from eboot	
SDOCM00080826	Adding Multiple BIN support	
SDOCM00080713	Boot from nand with 4-bit and 8-bit ECC xldrnand.bin does not work	
SDOCM00080645	Capturetest with pv enabled on am3517 causes target to hang	
SDOCM00080200	Loading bin files from SD card to flash	
SDOCM00080177	OMAP3530/DM3730: Device resumes immediately on suspend with SYSINTR -1	
SDOCM00080176	Linker error in BSPCFG (for WINCE_SDK 01.01.00)	
SDOCM00079743	several makefile.inc's in the bootloader subdirectory that copy the output file to an "F:" drive.	
SDOCM00076449	(Child) When in OFF mode, hfclkout should be turned off (currently it is still active)	
SDOCM00076433	(Child) When tvout is enabled, GFX demos on DVI/LCD slow down significantly	
SDOCM00076379	(Child) Tvout (S-Video/Composite output) stops functioning after a suspend/resume cycle	
	Mismatch information between bsp_opp_map.h and opm command output, CPU load policy	
SDOCM00076132	registry	
SDOCM00076110	OAL Timer Tests - GetVerifyIdle Time - Idle Time While Sleeping fails on AM3517	
	Suspend-resum manualy on OMAP3530 for many times(more than10) kills the platform or	
SDOCM00076086	doesn't respond anymore.	
SDOCM00075986	Some Nand test like "Create a 100 byte file with 1 cluster free" fail in build 14.	
SDOCM00075879	(Child) OMAP3530 ISP suspend/wake-up problem	
	(Child) With tvout and DVI enabled, starting media playback results in DVI screen blanking	
SDOCM00075872	out for a second.	
SDOCM00075870	(Child) Enabling WaitforVsync in Display driver causes performance degradation	
SDOCM00074298	00074298 Video capture preview does not work when VRFB is enabled	
SDOCM00074297	4297 IAMDroppedFrames interface of camera driver returns 0 values for all statistics	
SDOCM00074220	pCannot change the default USB function client via do.exe command usbFnSet	
SDOCM00072748	CETK: Flash Memory Read-write and performance - SD Card	
SDOCM00069780	KITL only works in polling mode	
SDOCM00069778	VMINI is not implemented (CETK Graphical Tool doesn't work)	

# 3.2. Rel 01\_01\_00 Patch 01

This release addresses multiple issues related to the installer/un-installer. There is no change to the source code and the binaries when compared to Rel 01\_01\_00

Following bugs have been fixed in this release:

<u>ID</u>	<u>Headline</u>
	(BSP_WINCE_ARM_A8)Previous version installed with no bump of ver num,
SDOCM00079752	uninstall will remove all versions of product
	(BSP_WINCE_ARM_A8) Uninstall of any one (BSP or GFX or DVSDK) will result
SDOCM00079749	in uninstalling all three
	BSP uninstall script incorrectly removes entire parent directory regardless of
SDOCM00079547	whether directory is empty or not

# 3.3. Rel 01\_01\_00

Following features have been added to this release:

1. Support for new hardware

- a. AM/DM3730 ES 1.2 silicon (Rev D)
- b. Power Module TPS65950A3 (Rev D)
- c. Zoom XAM3517AZCN (PG1.1)
- d. Application Board 1015189
- 2. Enabled Smart Reflex for AM/DM37X ES 1.2 Silicon when the characterization data is available.
- 3. Support for NAND ECC modes BCH 4-bit and BCH 8-bit. See BSP Limitations section for additional info.
- 4. Integrated ISP resizer into display driver for OMAP35x and OMAP37x devices so that h/w downscaling is performed even for resolutions such as 720p for which DSS cannot handle h/w downscaling.
- 5. Support for 720p codecs. Note that this is added for DM3730 devices only and one needs to have DVSDK 01.11.00 release to validate this.

In addition, following bugs have been fixed in this release

<u>ID</u>	<u>Headline</u>		
	On enabling and executing transcriber app, it complains that the 'Touch.dll'		
SDOCM00078172	name in the registry is not Transcriber's DLL		
	July monthly CE update fixes co-proc save/restore reg bug highlighted in		
SDOCM00078077	SDOCM00069239; No need for NEON workaround		
	VRFB (Virtual Rotated Frame Buffer) is not compatible with the some video		
SDOCM00078074	codecs provided by Microsoft.		
SDOCM00078071	Unable to set GPIO debounce time from touch driver		
	KITL over USB RNDIS doesnt work with OTG port on TPS65930 (but works on		
SDOCM00078069	00078069   ISP1507 on TI EVM)		
SDOCM00078061	Adding 4bit and 8bit ECC support for NAND device		
	hwcodecapi.h contains invalid characters resulting in compile error in some		
SDOCM00077424	countries		
SDOCM00077423	bug in the unified BSP - prcm_clock.c		
SDOCM00077422	TWL access bug in TWL_XXX functions in OAL		
SDOCM00077417	256M memory support should be added in AM35x BSP		
	OAL retail msgs to be enabled and network settings->kitl to be disabled by		
SDOCM00074515	default in SD eboot		
SDOCM00074514	4 Ethernet coming up is slow on am3517		
SDOCM00074513	Load NK.bin to NAND through SD boot		
SDOCM00074219	BSP_NOVRFB variable needs to be removed from AM35x batch file		
SDOCM00072602	DO.EXE Shell Extension failure		

#### 4. Distribution Contents

The BSP release installation file - BSP\_WINCE\_ARM\_A8\_01\_02\_00\_Source.exe contains the following files:

- Docs\BSP WinCE ARM A8 User Guide.pdf
  - User Guide for the BSP
- Docs\BSP\_WinCE\_ARM\_A8\_Quick\_Start\_Guide.pdf
  - Quick Start Guide for the BSP
- Docs\BSP\_WINCE\_ARM\_A8\_Demo\_Manifest.pdf
  - BSP demo package Manifest
- Docs\BSP\_WINCE\_ARM\_A8\_Manifest.pdf
  - BSP Manifest
- Docs\BSP\_WINCE\_ARM\_A8\_Demo\_Package\_License\_Agreement.pdf
  - Software License Agreement for the BSP demo package
- Docs\BSP\_WinCE\_ARM\_A8\_SLA.pdf
  - Software License Agreement for the BSP
- Sources\\*
  - BSP source files, OS Design, DVSDK and Graphics binaries
- o Misc\\*
  - DVSDK and Graphics demo files
- o Tools\\*
  - SD card and NAND flash utilities

#### 5. Installation Instructions

The BSP release installation file will install the source code and release documents to directory C:\TI\BSP\_WINCE\_ARM\_A8\_01\_02\_00\ by default. If the "install to \_WINCEROOT" option is selected during installation, then the Sources folder is installed under \_WINCEROOT (ex: C:\WINCE600) and docs/misc/tools folder are installed under C:\TI\BSP\_WINCE\_ARM\_A8\_01\_02. If using this option (install to \_WINCEROOT), then it is important that you backup and delete older version of ARM A8 BSP from

\_WINCEROOT folder, else you may have compilation issues (ex: dirs and sources file in the same folder, etc).

The Quick Start Guide contains full details of how to install, build and run the BSP for the respective processor.

## 6. Requirements

## 6.1. Required QFE's and Updates

- Windows Embedded CE 6.0 Product Update Rollup, December 31, 2006
- Windows Embedded CE 6.0 Product Update Rollup, December 31, 2007
- Windows Embedded CE 6.0 Product Update Rollup, December 31, 2008
- Windows Embedded CE 6.0 R3
- Windows Embedded CE 6.0 Product Update Rollup, December 31, 2009
- Windows Embedded CE 6.0 Monthly Update January 2010
- Windows Embedded CE 6.0 Monthly Update February 2010
- Windows Embedded CE 6.0 Monthly Update March 2010
- Windows Embedded CE 6.0 Monthly Update April 2010
- Windows Embedded CE 6.0 Monthly Update May 2010
- Windows Embedded CE 6.0 Monthly Update June 2010
- Windows Embedded CE 6.0 Monthly Update July 2010
- Windows Embedded CE 6.0 Monthly Update August 2010
- Windows Embedded CE 6.0 Monthly Update September 2010
- Windows Embedded CE 6.0 Monthly Update October 2010
- Windows Embedded CE 6.0 Monthly Update November 2010

## 6.2. Hardware Requirement

- For AM35x processor family:
  - AM3517 SOM-M2 processor board
  - eXperimenter Baseboard from LogicPD(<a href="http://www.logicpd.com/">http://www.logicpd.com/</a>)
  - Application board from LogicPD
- For OMAP35x processor family
  - OMAP3530 EVM (Rev G)<sup>Note</sup> from Mistral(http://www.mistralsolutions.com/)
  - Power Module from Mistral
  - OMAP35x processor Card from Mistral

Note: OMAP3530 EVM1 is not tested and is not officially supported in the BSP.

- For AM/DM processor family
  - Mistral OMAP3530 EVM (Rev G) from Mistral (same as above)
  - Power Module from Mistral (same as above)
  - AM/DM37x processor Card (Rev C) from Mistral

## 7. Feature Summary

The User Guide contains full details of the BSP functionality.

A summary of the features supported in this BSP release is available from <a href="http://processors.wiki.ti.com/index.php/WinCE-TIBSP">http://processors.wiki.ti.com/index.php/WinCE-TIBSP</a> Feature List

## 8. Test Summary

The BSP has been tested using a combination of Microsoft CETK, functional test and custom test utilities.

The BSP has been through the full system test and validation process to validate all the BSP functionality. Details of the Known Issues are available in Section 9 below.

The BSP has been tested with the following software and hardware revisions:

- Zoom OMAP3517ZCN (PG1.0) EVM kit (1013686 Rev 5)
  - Processor card: 1013636 Rev 7
  - eXperimenter Baseboard: 1013702 Rev 4
  - Application Board: 1013690 Rev 4\*\*
  - o 4.3" WQVGA LCD: 1012041 Rev C
- Zoom XAM3517ZCN (PG1.0) EVM kit (1014470 Rev D)
  - Processor card: 1014471 Rev D
  - o eXperimenter Baseboard: 1014472 Rev B
  - o Application Board: 1014473 Rev C\*\*
  - o 4.3" WQVGA LCD: 1012041 Rev C
- Zoom XAM3517AZCN (PG1.1) EVM kit (1014470 Rev D)
  - Processor card: 1017100 Rev C
  - o eXperimenter Baseboard: 1014472 Rev B
  - Application Board: 1015189 Rev C
  - o 4.3" WQVGA LCD: 1012041 Rev C
- Mistral OMAP35x EVM kit
  - Main board: Rev G
  - o Power Module: Rev D
  - OMAP35xx processor card: Rev C
  - OMAP37xx(ES1.2) processor card: Rev D
- Windows CE 6.0 R3 with monthly updates to August 2010

In addition to functionality, performance was also measured, you can found out the performance data from the following link:

http://processors.wiki.ti.com/index.php/WinCE Comparative Benchmarks

\*\*Note: For older revisions of App boards, video input driver functionality will not work out of the box in this release. Users will need to modify the video input driver and rebuild BSP, if using older app boards. See ARM A8 User Guide (Section Video Input driver) for more details.

http://processors.wiki.ti.com/index.php/WinCE-BSP\_ARM-A8\_User\_Guide#Video\_input\_Driver\_

#### 9. Limitations

Due to hardware and software limitations, some of the feature may not work properly. See current list below. For an updated list, please visit <a href="http://processors.wiki.ti.com/index.php/WinCE\_BSP\_ARM-A8">http://processors.wiki.ti.com/index.php/WinCE\_BSP\_ARM-A8</a> Known Limitations

#### 9.1. BSP Limitations related to Hardware

This section lists issues in the ARM-A8 WinCE BSP due to TI EVM limitations. If a particular feature listed below is desired, then customers can modify their board design accordingly.

- SDOCM00073563 write protection is not working on slot 2 (AM3517). GPIO 176 is used by SDHC2 for its WP detect. This is also used by LCD module for PANEL\_POWER. In case of LCD, this GPIO should be configured as output but for SDHC2, this should be configured as input. Its becasue of this pin mux conflict, WP is disabled for SDHC2. To enable the write protection, PAD configuration(bsp\_padcfg.h) for MCSPI\_CS2 needs to be added in MMC2\_PADS and "CardWPGPIO" for slot 2 needs to be set in sdhc.reg.
- SDOCM00074846 warm reboot doesnt work when booting from SD card on AM3517. One
  would need to mod the board to achieve the right SYS\_BOOT sequence to boot from MMC1 for
  warm boot.
- **SDOCM00075349** CEStress fails on DM3730 after about 30 minutes device is inactive. Issue appears to be an EVM issue as some boards work fine and some don't.
- **SDOCM00075381** Prefetch abort error (or application hangs otherwise) on omap35xx after watchdog timer times out and app is coming up. Issue appears to be an EVM issue as some boards work fine & some don't.
- **SDOCM00076091** Voltage drop on VDD2 for most of OPPs is not correct. The reading is much higher than expected. Again EVM limitation.
- SDOCM00070568 NOR XLDR doesn't boot (AM3517). The NAND\_nCS line comes from the application board to the SOM and is equivalent to GPMC\_nCS2 when BOOT\_SRC is set properly. The problem is that the boot rom code does not setup GPMC\_nCS2 and leaves the pad unused (it acts as unconnected) and therefore the presence of the application board or its absence doesn't change the behavior of this line during the boot rom code execution. As a result, accessing CSO still accesses the NAND (and actually the NOR in parallel) and returns invalid data.

- SDOCM00073565 Cannot test low voltage MMC cards (AM3517). In order to test the lower voltage cards, you will have to move the R220 to R221 to switch the SD slot to the 1.8 V rail instead of the 3.3V rail. You will then have to change the slot's voltage capabilities flag to add the 1.8 V range to it.
- **SDOCM00075958** Verify Get NLED Count fail on dm3730. EVM limitation. NLED driver for AM/DM37x is disabled. The Pinmux for PROC\_ACT LED GPIO (GPIO8) conflicts with DSS\_data23 on DM3730.
- **SDOCM00078379** BCH 4bit ECC does not work on OMAP3530 , AM/DM 3730 PG1.0 and AM3517 PG1.0. Chip limitation. The issue is fixed in chip version AM/DM3730 PG1.1 and AM3517 PG1.1. OMAP3530 chip does not have the fix.
- **SDOCM00076456** Video encode performance using capturetest app on omap3530 is lower than dm3730. Performance is expected to be lower on omap3530. This IR documents the information along with some numbers in comparison with performance on dm3730. Scenario: Codec H264 BitRate 4000000bps Resolution 720x480@30 Output written to RAM, VideoInput is  $\Delta V$
- AM35X SD/MMC 2 SD/MMC slot 2 can not be recognized on some AM3517 EVM. Signals of MMC2 are conflicting with wireless module.
- **DISPLAY ROTATION** In DVI mode, when desktop is rotated by 90 degrees, multimedia playout cause corrupted video and audio playout
- VIDEO INPUT AM35x only. By default, BSP 01.02.00 and later can only work with App board revision 1015189 and later whereas BSP 01.01.00 and earlier versions of BSP can work with old App board revisions. To change this default behavior, see Video Input Driver section in BSP ARM A8 User Guide.

#### 9.2. BSP Limitations related to Microsoft WinCE Kernel

This section describes issues in ARM-A8 BSP due to bugs identified in either WinCE private kernel code and/or CETK test case.

- **SDOCM00068743** Partition Driver Test CETK fails for test ID 5103 R/W and bounds check disk partition data
- SDOCM00068741 OAL Cache CETK test OAL Data Cache Size Calculation test fails (test case ID 1008)
- SDOCM00071488 CETK:Storage Device Block Driver API Test 4024 fail and Storage Block
  Driver Read/Write Test Buffer Sizes: (8X) test fail. Tthe failure is due to a wrong error code
  (ERROR\_INVALID\_PARAMETER) which is returned by the WINCE private FAL code and not the
  NAND FMD layer.
- SDOCM00072747 Storage Block Driver Read/Write Test Buffer Sizes: (8X) test fails -NANDFlash.

### 9.3. Other BSP Limitations

- SDOCM00074296 Capture driver supports only interlaced video input
- **SDOCM00078776** BCH software decoder returns "-1" occasionally.
- **TV OUT** Surfaces greater than 800x600 in resolution cannot be displayed on TV output.
- **ISP RESIZER in DSS** When TV out is enabled, it is advisable to disable use of ISP resizer in display (DSS) driver (available as catalog entry).

#### **10.**Known Issues

Latest issues list can be tracked in the TI bug database

https://cqweb.ext.ti.com/cqweb/main?command=GenerateMainFrame&service=CQ&schema=SDo-Web&contextid=SDOWP&entityDefName=IncidentReport&username=readonly&password=readonly&queryID=34403363

Here is a brief note on what various states in this database mean:

- Open: Problem has been submitted recently but has not been looked at by Eng (may or may not be real issue)
- Accepted: Engineering has accepted the problem as an issue to look into
- Planned: Fix has been implemented but has not been released or verified by QA
- Fixed: Resolution implemented and fix verified independently by QA

<u>ID</u>	<u>Headline</u>	Targets
	CETK Touch Panel test 8007( Driver does not support	
SDOCM00071258	TouchPanelInitializeCursor) fail	ALL
SDOCM00071359	CETK - NAND - File System Driver	ALL
	System hangs when not exiting an OpenGL application	
SDOCM00074380	gracefully	ALL
	When running imaging codec cetk tests, certain exceptions in	
SDOCM00074635	coredll.dll are printed on console	ALL
SDOCM00074643	Camera CETK failures	ALL
	USB Mass Storage takes a long time to mount on Windows	
SDOCM00075290	Vista/7	ALL
	With 1280x720 DVI resolution, output is disturbed on omap3530	
SDOCM00075370	and red on am3517, during image download	ALL
	Green band at bottom and blue line on rightmost end of capture	
SDOCM00075671	window	ALL
	GDI tests on AM3517 - DVI mode leads to display toggling	
SDOCM00076059	between on and off and test not completing	ALL
000011000	(Child) Switching TVout (composite/S-Video) on/off doesn't work	
SDOCM00076382	always while DVI is on	ALL
SDOCM00078776	BCH software decoder returns "-1" occasionally	ALL
000000000000000000000000000000000000000	Work item - would like to know why component capture preview	
SDOCM00080647	shows two outputs side-by-side unlike AV or SVideo capture	ALL
0000110000010	Capturetest with "raw" option should allow output to be saved in	
SDOCM00080648	an output file	ALL
CD COM0000707	MaskBlt GDI CETK test results in data abort errors and fails in	A
SDOCM00080737	DVI mode if '/noresize' option is used	ALL
SDOCM00081308	Enabling Persistent storage may not work as is with BinFS (multibin) builds	ALL
SDOCM00075809	Random Data Abort on GPTimer1 register access	AM/DM3730
CDOCM00070000	(Child) When BSP_XRPLUGIN_DDRAW is turned on, XAML	AM/DM0700/OMAD0500
SDOCM00072603	perf apps doesn't work (TTM Issue on OMAP 6.14 release)	AM/DM3730/OMAP3530
SDOCM00072605	(Child) When the device hangs, USB RNDIS KITL will not work until PC is re-booted (TTM Issue on OMAP 6.14 release)	AM/DM3730/OMAP3530
SDOCM00072810	Waveform Audio Driver - mixerOpen function fails on omap3530	AM/DM3730/OMAP3530
SDOCM00073009	Waveform Audio Loopback Test - OMAP3530 - cracks in output	AM/DM3730/OMAP3530
0000100070000	USB-Forum OPT Tests: OMAP3530 Fails a significant number	AAA/DAAG700/OAAA D0500
SDOCM00073366	of tests	AM/DM3730/OMAP3530

	Implementation for Advisory 3.1.1.176 Accesses to DDR Stall in	
SDOCM00074376	SDRC After a Warm-reset	AM/DM3730/OMAP3530
	(Child) VBus Error seen occasionally causing OTG port not to	
SDOCM00075874	function	AM/DM3730/OMAP3530
SDOCM00075881	(Child) EHCI inconsistencies - summary	AM/DM3730/OMAP3530
	USB - CETK Storage Device Block Driver Benchmark Test	
SDOCM00076102	Failure	AM/DM3730/OMAP3530
	(Child) Active Sync connection can't be established after reset	
SDOCM00076438	through WARM_RST button when plugged into USB OTG port.	AM/DM3730/OMAP3530
	Capturetest - stream statistics - number of captured samples	
SDOCM00080646	and average frame size are always 0	AM/DM3730/OMAP3530
000011000000	Suspend and Resume makes the system hang for MultiBin	414/D140700/0144/D0500
SDOCM00080828	image	AM/DM3730/OMAP3530
CDOCM00071006	CAN - loopback feature in WinCE driver will enable testing low	AM0517
SDOCM00071296	bit rates like 10K	AM3517
SDOCM00071352	CETK - DirectShow Playback and Latency	AM3517
SDOCM00071356	CETK - Image Codec	AM3517
CDOCM00071004	There is error messages when running CETK OAL interrupt	AM0517
SDOCM00071904	IOCTL kernel tests  Provide way to stop refreshing WDT and way to set WDT	AM3517
SDOCM00072121	timeout value instead of modifying source code	AM3517
3D0010100072121	AIC23 in master mode is required to verify McBSP in slave	AWISSTY
SDOCM00072426	mode functionality	AM3517
0B00M00072120	CAN driver requirement - powerup and powerdown APIs are	71110017
SDOCM00073165	currently stubs - need to be implemented	AM3517
SDOCM00073296	DirectDraw CETK video test cases (ID 400 to 420) are skipping	AM3517
	USB-Forum Tests - When USB test mode environmental	
SDOCM00073446	variable is enable, the build fails with an error.	AM3517
	Canbenchrx app - need clarifications and batch files to use this	
SDOCM00073452	арр	AM3517
SDOCM00073453	BUS_OFF error seen after dynamic baud rate change to 50000	AM3517
	USB-Audio Streaming - Streaming to/from USB	
SDOCM00073493	speakers/microphone does not work.	AM3517
SDOCM00074632	Battery API test - one test fails on AM3517	AM3517
00001100071010	warm reboot doesnt work when booting from SD card on	
SDOCM00074846	AM3517	AM3517
SDOCM00074849	IMGNOCLAIBRATION flag doesnt exist for AM35XX BSP	AM3517
SDOCM00074949	Camera Driver SelectXXX function not implemented properly	AM3517
SDOCM00075108	OAL CETK Test fails - Compare All Three Timers- Busy Sleep	AM3517
000011000	Touchscreen becomes no response intermittently after suspend	
SDOCM00075941	and resume	AM3517
CDOCM00070700	Ethernet link's disconnect status reporting time is longer than the	AM0517
SDOCM00078708	connect status reporting time GDI Q-score has dropped for am3517 when comparing 1.01	AM3517
SDOCM00080732	versus 1.02 release results	AM3517
3500M00000732	AM35x Board crashes randomly during Boot up with multibin	/ NVIOO I /
SDOCM00080827	supported image	AM3517
2= 0 30000027	AM3517: Capturetest with preview enabled causes display and	
SDOCM00080855	system to lock up when VRFB is enabled	AM3517
SDOCM00080954	Audio driver does not work with fastboot image on AM3517	AM3517
	BSP Information from control panel shows CPU speed to be 0	
SDOCM00081015	MHz on AM3517	AM3517
SDOCM00069252	If doing Suspend while Media playback is active, DSP does not	DM3730/OMAP3530

	go into suspend and this results in higher power consumption	
	CaptureTest application: High ARM utilization seen when	
SDOCM00074300	preview is enabled and preview window is minimized	DM3730/OMAP3530
	Data abort seen when going into suspend state while WMP is	
SDOCM00074639	playing video file from SD card (which uses DSP codec)	DM3730/OMAP3530
	ARM utilization remains at above 30% even after one or two	
SDOCM00076080	minutes after the target comes up	OMAP3530

## 11.Support

For technical support, please post to the TI e2e WinCE community forum

http://e2e.ti.com/support/embedded/f/353.aspx

Forum reported issues that are reproducible on the EVM will be entered into TI bug database and can be tracked here

https://cqweb.ext.ti.com/cqweb/main?command=GenerateMainFrame&service=CQ&schema=SDo-Web&contextid=SDOWP&entityDefName=IncidentReport&username=readonly&password=readonly&queryID=34403363

Note: If prompted for login/password, please close the browser and click on the link again.

For latest information on the BSP, please TI WINCE BSP wiki:

http://processors.wiki.ti.com/index.php/WinCE-TIBSP Handbook

Users new to Windows Embedded CE6 can start from the following link:

http://www.microsoft.com/windowsembedded/en-us/products/windowsce/default.mspx