

# MPEG4 Simple Profile Encoder

## Version 02.04.01

### Release Notes

**January 2013**

#### Build ID: 02.04.01.02

The release note is divided into the following sections:

- [New In This Release](#)
- [Validation Information](#)
- [Fixed In This Release](#)
- [Known Issues](#)

#### New In This Release

#### Validation Information

Release Configuration	Description	Validation Platform
C6678_SP_001	MPEG4 Simple Profile Encoder on TMS320C6678 EVM	TMS320C6678 <a href="#">[Datasheet]</a> <a href="#">[User Guide]</a>

This release is validated on the following:

- TMS320C6678
  - Framework Component (FC) version 3.22.03.09
  - DSP/BIOS™ version 6.33.04.39
  - Code Generation Tool version 7.4.0
  - XDC Tools version 3.23.04.27
  - BIOS IPC version 1.24.02.27
  - XDIAS version 7.22.00.03
  - EDMA3 LLD version 02.11.05.02



## Fixed In This Release

Defect ID	Description	Applicable Release Configuration
SDOCM00097858	Use FC lite package and remove dependency on fctools which exists in FC full package	C6678_SP_001

## Known Issues

Defect ID	Description	Applicable Release Configuration
SDOCM00025676	For low bit rates and for few streams, encoding with H.263 mode ON and RC enabled gives poor visual quality..	C6678_SP_001
SDOCM00026327	Blockiness is seen when encoding flat areas for low bit rate encoding.	C6678_SP_001
SDOCM00052474	Breathing artifacts seen for few streams - this is due to lower I frame quality.	C6678_SP_001
SDOCM00026347	For few Streams, VBV underflow / overflow error reported by Vprove for MPEG4 encoded streams	C6678_SP_001
SDOCM00065744	Complete Testing for RateControlMethod = 9 (Constant Bit Rate) is not yet done.	C6678_SP_001
SDOCM00082368	EDMA related code cleanup is needed for MPEG4 encoder	C6678_SP_001