

TVP5160 V04.04.02 Release Notes

Digital Video Department

IMPORTANT NOTICE

Texas Instruments (TI) reserves the right to make changes to or to discontinue any semiconductor product or service identified in this publication without notice. TI advises its customer to obtain the latest version of the relevant information to verify, before placing orders, that the information being relied on is current.

TI warrants performance of its semiconductor products to current specifications in accordance with TI's standard warranty. Testing and other quality control techniques are utilized to the extent TI deems necessary to support this warranty. Unless mandated by government requirements, specific testing of all parameters of each device is not necessarily performed.

TI assumes no liability for TI applications assistance, customer product design, software performance, or infringement of patents or services described herein. Nor does TI warrant or represent that any license, express or implied, is granted under any patent right, copyright, mask work right, or any other intellectual property right of TI covering or relating to any combination, machine, or process in which such semiconductor products or services might be used.

Introduction

This document discusses the improvements implemented in the TVP5160 v04.04.01 RAM from The TVP5160 ROM v04.00.

Firmware Issues

This section discusses the Firmware issues addressed in TVP5160 v04.04.02 RAM code. TVP5160 RAM V04.04.02 is based on V04.04.01.

Vertical Bounce

When playing certain Play Station 2 disks the TVP5160 would cause a vertical bounce in the output.

This issue is fixed in RAM version 04.04.02.