

# EDMA3 Driver

Release version 02.11.12.XX

## Release Notes

May 30, 2014

The product release notes in this document are for EDMA3 Driver, which is a part of the EDMA3 Low Level Driver package. EDMA3 Driver is a functional library providing APIs for programming, scheduling and synchronizing with EDMA transfers and many more. The EDMA3 Driver is made generic across SoCs and across Operating Systems.

---

**TABLE OF CONTENTS**

---

<b>1</b>	<b>In This Release .....</b>	<b>3</b>
<b>2</b>	<b>Out-of-Box Contents .....</b>	<b>4</b>
<b>3</b>	<b>Known Issues.....</b>	<b>5</b>
<b>4</b>	<b>Limitations .....</b>	<b>6</b>
<b>5</b>	<b>Fixed In This Release .....</b>	<b>7</b>
<b>6</b>	<b>Revision history .....</b>	<b>8</b>
	<b>Appendix: Changes from last release .....</b>	<b>10</b>

## **1 In This Release**

This is the 02.11.12.XX release of EDMA3 Driver and contains libraries, sample initialization libraries, standalone sample applications and support documents.

This release contains sample OS adaptation layer for BIOS 6, which could be used by BIOS 6 based applications.

## 2 Out-of-Box Contents

edma3\_llid\_02\_11\_12\_16.tar.gz contains following:

1.
  - Source code for EDMA3 Resource Manager, Driver and other necessary abstractions.
  - Project files (DSP/BIOS™), CCS4 build files, XDC package.bld files (for supporting getlibs function) and all Makerules and Makefiles, to build EDMA3 package in host environment. Please note from this point of time, libraries can be built using Makefiles only. Hence libraries need to be built through command prompt using gmake command (Please refer the user guide available with this release for detailed build instructions).
  - The above mentioned items are located inside the <installation dir>\edma3\_llid\_02\_11\_12\_XX\ directory.
  - Please note that the CCS setup files and GEL files are NOT provided with this release and this would be available with latest CCSv4 releases or from EVM manufacturer.
2. Release Notes (this document) providing an overview of this release.
3. User Guide and data sheets.
4. EDMA3 Driver API (generated) documentation in CHM format.

### 3 Known Issues

<b>1.</b>	<b>Instrumentation (all components)</b>
<b>Release Note</b>	
Instrumentation code is not yet implemented as the XDC/CCSv4 version at the point of development did not support RTA and instrumentation APIs.	
<b>Workaround</b>	
None	

<b>2.</b>	<b>EDMA3 hardware doesn't works properly in FIFO mode with all the controllers.</b>
<b>Release Note</b>	
Very few peripherals support EDMA3 FIFO mode. EMIF controller doesn't support the same. So EDMA3 CANNOT be used in FIFO mode for doing a mem-2-mem data transfers, EDMA3 being configured in the FIFO mode. Applications trying to use EDMA3 in FIFO mode should first check their respective peripheral-controller document for this mode support.	
<b>Workaround</b>	
None	

<b>3.</b>	<b>PingPong Example Fails for certain EDMA instances for some DSP cores in Release mode only.</b>
<b>Release Note</b>	
PingPong example fails for certain EDMA Instances for some DSP cores in Release Mode only. It passes in the Debug mode.	
<b>Workaround</b>	
None	

<b>4.</b>	ARM 9 support for OMAPL138 is not available on Make based build of EDMA3LLD
<b>Workaround</b>	
None	

<b>5.</b>	The following IR is raised on this release.
<b>IR# SDSCM00039169</b> EDMA3 Example fails for following Big Endian Simulators: tci6608-sim/tci6616-sim	
<b>Workaround</b>	
None	

#### **4    Limitations**

None.

## 5 Fixed In This Release

<b>IR</b>	<b>Description</b>
SDOCM00106346	edma3lld needs to be compiled with --mem_model:data=far for use with OpenCL
SDOCM00108028	Add Support for tda3xx platform in edma3lld
SDOCM00108029	Add Support for DRA72x platform in edma3lld

## 6 Revision history

<b>Date</b>	<b>Author</b>	<b>Comments</b>	<b>Version</b>
Oct 16, 2008	Anuj Aggarwal	First release supporting platform DA830 on BIOS 6.	02.00.00.XX
June 3, 2009	Anuj Aggarwal	Patch release for DA830 platform on BIOS 6.	02.00.01.XX
Dec 7, 2009	Anuj Aggarwal	Migration to BSD license and support added for TCI6498. See section 1 for more details.	02.10.00.XX
Apr 9, 2010	Imtiaz SMA	Support for the C6748 and OMAPL138 (DSP only) is added. See section 1 for more details.	02.10.01.xx
May 12, 2010	Vinay Nooji	K Support for the OMAPL138 ARM has been added.	02.10.02.XX
Sep 6, 2010	Sundaram Raju	Support for the TI816X Simulator & platform, C6472 & TCI6486 platform and TI814X platform have been added.	02.10.03.XX
Oct 12, 2010	Sundaram Raju	Support for C66x(ELF) in Generic library of Resource Manager and bug fixes	02.10.04.XX
Feb 02, 2011	Sundaram Raju	Support for Make based build for all the libraries and sample applications	02.11.00.XX
Feb 15, 2011	Raghu Nambiath  Sundaram Raju	Support for C66x target for all the libraries and sample applications	02.11.01.XX
May 24, 2011	Prasad Konnur	Addition of TI816x-m3vpss and TI816x-m3video platforms to EDMA3LLD	02.11.02.XX
Nov 15, 2011	Prasad Konnur	Addition of M3 support for TI814X and A8 support for TI816X	02.11.03.XX
Jan 27, 2012	Murtaza Gaadiwala	Addition of Appleton (TCI6614) support	02.11.04.XX
Mar 9, 2012	Prasad	Addition of TI811X (TI811X) support	02.11.05.XX



May 10, 2012	Murtaza Gaadiwala	Addition of Gauss (C6657) and Kepler (TCI6634) support	02.11.05.02
Aug 10, 2012	Prasad Konnur	Bug fixes	02.11.06.01
MaY 13, 2013	Prasad Konnur	Addition of TDA2XX support	02.11.07.03
May 17, 2013	Murtaza Gaadiwala	Addition of TCI6638K2K support	02.11.07.04
June 20, 2013	Prasad Konnur	TDA2XX return region number at runtime based on core	02.11.08.XX
July 18, 2013	Murtaza Gaadiwala	Addition of TCI6636K2H support	02.11.09.XX
Sept 23, 2013	Sivaraj R	Addition of GCC Compiler build for A8 for Centaurus and bug fix	02.11.10.XX
Dec 20, 2013	Arvind S	Ported EDMA Ild to EVE core to access EVE internal EDMA instance.	02.11.11.XX
Dec 27, 2013	Arvind S	Bug fixes	02.11.11.XX
Jan 7, 2014	Arvind S	Removed warnings and bug fix	02.11.11.XX
Feb 19, 2014	Ivan P	Merged in user space support for Keystone 2 devices	02.11.11.XX
May 30, 2014	Prasad Konnur	Addition of TDA3xx and DRA72x platform support	02.11.12.XX

## **Appendix: Changes from last release**

### **Changes from 02.11.11.13 Release to 02.11.11.15 Release:**

- i. Added support for TDA3xx and DRA72x platforms

### **Changes from 02.11.11.13 Release to 02.11.11.15 Release:**

- i. Fixed following IR:
  - 1. SDOCM00106346 - edma3lld needs to be compiled with --mem\_model:data=far for use with OpenCL
- ii. Added User Space libraries and examples for Keystone 2 Devices

### **Changes from 02.11.10.09 Release to 02.11.11.13 Releases:**

- i. Fixed following IR:
  - 1. SDOCM00104308 - Add Ti814x sample app, the unregisterEdma3Interrupts causes an exception because error interrupts were not assigned for M3 builds.
  - 2. SDOCM00105689 - EDMA3 LLD support for official DRA7xx platform is broken.
  - 3. SDOCM00105739 - Add Support for EVE internal EDMA in EDMA3 LLD
  - 4. SDOCM00105829 - Remove build warnings and C++ warning
  - 5. SDOCM00105832 - Tear down sequence in standalone example is improper

### **Changes from 02.11.09.08 Release to 02.11.10.09 Releases:**

- i. Fixed following IR:
  - 1. OMAP500298778 - EDMA3 LLD module is not able use with A15 - Support EDMA3 LLD to get the A15 libraries build with the '.aa15fg' extension
  - 2. OMAP500299498 - GCC support on A8 for Centaurus for EDMA LLD

### **Changes from 02.11.08.06 Release to 02.11.09.08 Releases:**

- i. Fixed following IR:
  - 1. SDOCM00102368 - EDMA3 LLD: Add support for TCI6636K2H target
  - 2. SDOCM00102388 - Section placement of EDMA3LLD needs to be adjusted in order to interop w/ OpenMP

### **Changes from 02.11.07.04 Release to 02.11.08.06 Releases:**

- i. Fixed following IR:
  - 1. SDOCM00101975 - EDMA3 LLD compatibility key causing unnecessary build failure
  - 2. SDOCM00102051 - Determining the core by reading from a core id or device id register (if possible), instead of compile time definitions.

3. SDOCM00102486 - [Vayu McSPI ] McSPI Applications does not work without EDMA Channel Mapping.

**Changes from 02.11.07.03 Release to 02.11.07.04 Releases:**

- i. Fixed following IR:
  1. SDOCM00100731 – Addition of TCI6638K2K platform support

**Changes from 02.11.06.01 Release to 02.11.07.03 Releases:**

- i. Fixed following IRs:
  1. SDOCM00090630 – Addition of platform TDA2XX
  2. OMAP500293688 - eDMA\_LLD\_02.11.06.01 build steps and missing tools update in Rules.mk
  3. SDOCM00101256 - Update M4 base address to 0x6330 0000

**Changes from 02.11.05.02 Release to 02.11.06.01 Releases:**

- i. Fixed following IRs:
  1. SDOCM00090630 – Documentation update: workaround for building on windows 7
  2. SDOCM00092324 – EDMA\_DRV\_SAMPLE [C6A811x]: The cross bar event is not initialized for platform C6A811x (J5Eco)
  3. SDOCM00092758 – EDMA3 LLD: edma3\_drv\_bios6\_c6472\_st\_sample and edma3\_drv\_bios6\_c6472be\_st\_sample projects do not link
  4. SDOCM00092759 – EDMA3 LLD: edma3\_drv\_bios6\_c6748\_st\_sample does not build

**Changes from 02.11.05.01 Release to 02.11.05.02 Releases:**

- i. New Features in this release
  1. SDOCM00090449 – C6657 Platform addition in EDMA3LLD
  2. SDOCM00090675 – TCI6634 Platform addition in EDMA3LLD

**Changes from 02.11.04 Release to 02.11.05 Releases:**

- i. New Features in this release
  1. SDOCM00090258 – TI811X Platform addition in EDMA3LLD.
- ii. Fixed following IRs:
  1. SDOCM00088790 – Documentation update.

**Changes from 02.11.03 Release to 02.11.04 Releases:**

- i. New Features in this release
  1. SDOCM00088699 – Appleton (TCI6614) support in EDMA3 LLD.
- ii. Fixed following IRs:
  1. SDOCM00088023 – Warnings in building edma libs.

**Changes from 02.11.02 Release to 02.11.03 Releases:**

- 
- i. New Features in this release
    - 1. TIDSP00012765 – Addition of TI816x-m3vpss and TI816x-m3video platform to EDMA3LLD.
    - 2. TIDSP00012766 – Addition of A8 support for TI816X in EDMA3 LLD
  - ii. Fixed following IRs:
    - 1. SDOCM00084073: SYS/BIOS version of LLD package should not require ti.sysbios.ipc which is deprecated and will be removed in SYS/BIOS 6.33
    - 2. SDOCM00086386: getlibs in package.xs should search library based on device name
    - 3. SDOCM00086391: Thread safety issue with EDMA
    - 4. SDOCM00084227: Enhancement - provide PLATFORM specific libs: examples: targets
    - 5. SDOCM00086397: Single default cfg file for multile cores in TI816X and TI814X in drv sample
    - 6. SDOCM00086492: EMRH access done in edma3CCErrorHandler() for devices not having high register for EMR
    - 7. SDOCM00086496: In EDMA3\_RM\_unregisterTccCb() driver tries to update array at invalid position
    - 8. SDOCM00086934: same interrupt number is used for all TC error

### **Changes from 02.11.01 Release to 02.11.02 Releases:**

- i. New Features in this release
  - 1. TIDSP00012625 – Addition of TI816x-m3vpss and TI816x-m3video platform to EDMA3LLD.
- ii. Fixed following IRs:
  - 1. SDOCM00080618: ti.platforms.evmTI816X and evmTI814X need to be supported
  - 2. SDOCM00080034: CC Base Address in TI814X configuration in ti/sdo/edma3/rm/src/configs is wrong
  - 3. SDOCM00081696: EDMA package gives error while including as XDC package
  - 4. SDOCM00081697: release build of EDMA3LLD build with GENERIC flag defined

### **Changes from 02.11.00 Release to 02.11.01 Releases:**

- i. New Features in this release

1. TIDSP00012604 – Addition of C66x targets and platforms to EDMA3LLD.
- ii. Fixed following IRs:
  1. SDOCM00078641: C66x support for generic RM library for Make based build of EDMA3LLD
  2. SDOCM00078808: EDMA LLD example fails for multi core run for TCI6486 target
  3. SDOCM00078797: Problems with using Generic RM library on EDMA3LLD

#### **Changes from 02.10.04 Release to 02.11.00 Releases:**

- i. New Features in this release
  1. TIDSP00012597 – Support for Make based build is implemented.
- ii. Fixed following IRs:
  1. SDOCM00075906: EDMA3LLD release not appearing as option in the eclipse plug-in in CCSv4 when new release is installed
  2. SDOCM00074338: EDMA3 LLD for TI814X doesn't have pre-built lib for Elf targets
  3. SDOCM00078607: Same library files picked up for both SIM and EVM TI816x by the package.xs

#### **Changes from 02.10.03 Release to 02.10.04 Releases:**

- i. Implemented the following ECNs:
  1. TIDSP00012597 - Support for Make based build is implemented.
- ii. Fixed the following IRs:
  1. SDOCM00075906 - EDMA3LLD release not appearing as option in the eclipse plug-in in CCSv4 when new release is installed
  2. SDOCM00074338 - EDMA3 LLD for TI814X doesn't have pre-built lib for Elf targets
  3. SDOCM00078607 - Same library files picked up for both SIM and EVM TI816x by the package.xs

#### **Changes from 02.10.03 Release to 02.10.04 Releases:**

- i. Fixed the following IRs:
  1. SDOCM00074290 - EDMA3LLD should not ship config.bld in the 'packages\' folder.

#### **Changes from 02.10.02 Release to 02.10.03 Releases:**

- i. Implemented the following ECNs:
  1. TIDSP00012436 - Support for the TI816X Simulator for BIOS6 has been implemented.
  2. TIDSP00012435 - Support for the TI816X platform for BIOS6 has been implemented.

3. TIDSP00012434 - Support for the C6472 & TCI6486 platform for BIOS6 has been implemented.
  4. TIDSP00012461 - Support for the TI814X platform for BIOS6 has been implemented.
- ii. Fixed the following IRs:
1. SDOCM00074153 - EDMA3LLD libraries for Nyquist are not building with BIOS 6.30.02.42
  2. SDOCM00074184 - Warnings appear while building the libraires and example projects of EDMA3LLD with BIOS 6.30.02.42

**Changes from 02.10.01 Release to 02.10.02 Releases:**

- i. Implemented the following ECNs:
1. TIDSP00012328 - Support for the OMAPL138 ARM platform.

**Changes from 02.10.00 Release to 02.10.01 Releases:**

- i. Implemented the following ECNs:
1. TIDSP00000000 - Support for the C6748 and OMAPL138 platforms.
- ii. Fixed the following IRs:
1. SDOCM00068784 - The package.xs files should get the library extension from the xdc variable and should not be hard coded.

**Changes from 02.00.00 Release to 02.10.00 Releases:**

- i. Implemented the following ECNs:
1. TIDSP00012004 - Migration to new BSD license has been implemented.
  2. TIDSP00012060 - Add TCI6498 support on BIOS6 has been implemented.
  3. TIDSP00012061 - Support for Big Endian platforms has been implemented.
  4. TIDSP00012062 - Specific link channel can be requested using requestChannel API has been implemented.
  5. TIDSP00012063 - Link channels can have TCC code has been implemented.
  6. TIDSP00012064 - New API to register callback function in EDMA3 driver has been implemented.
  7. TIDSP00012065 - New API to check the status of a given DMA/QDMA channel has been implemented.
  8. TIDSP00012079 - Signature change for EDMA3 initialization API present in the sample example has been implemented.
  9. TIDSP00012080 - API required to enable error interrupts for EDMA3 Transfer Controller has been implemented.
  10. TIDSP00012081 - DRAE registers programmed for TCCs while registering callback functions has been implemented.

11. TIDSP00012094 - Linux installer of EDMA3 LLD has been implemented.
- ii. Fixed the following IRs:
  1. SDOCM00060737 - EDMA3 needs to show up as RTSC product in CCSv4

**Changes from 02.00.00 Release to 02.00.01 Releases:**

Patch release fixing IRs and implementing ECNs in EDMA3 Driver.